

Appendix A

South Huntley Creek Photo Log





Photograph 1 ↑
Site 1 – Pool of standing water on the northeast side of William Mooney Road



Photograph 2 ↑
Site 1 – Agricultural ditch on the southwest side of William Mooney Road



Photograph 3 ↑
Site 2 – Looking upstream, stream flows through farm fields including use by animals



Photograph 4 ↑
Site 2 – Looking downstream



Photograph 5 ↑
Flooded ditch near intersection of Richardson Side Road and William Mooney Road, looking upstream



Photograph 6 ↑
Ditch flowing along Richardson Side Road



Photograph 7 ↑
Site 3 – South Huntley Creek, west side of
Carp Road, looking upstream



Photograph 8 ↑
Site 3 – South Huntley Creek, east side of Carp Road,
looking downstream before stream enters quarry property



Photograph 9 ↑
Site 4 – South Huntley Creek, southeast side of
Richardson Side Road, looking upstream



Photograph 10 ↑
Site 4 – South Huntley Creek, northwest side of
Richardson Side Road, looking downstream



Photograph 11 ↑
Site 6 – South Huntley Creek, west side of
Newill Place, looking upstream



Photograph 12 ↑
Site 6 – South Huntley Creek, east side of
Newill Place, looking downstream



Photograph 13 ↑
Site 5 – Huntley Creek, west side of
Oak Creek Road, looking upstream



Photograph 14 ↑
Site 5 – Huntley Creek, east side of
Oak Creek Road, looking downstream



Photograph 15 ↑
Mottled Sculpin caught at Site 4