



Photograph 1 ↑

Site 1 – Dry area where pool of standing water used to be on the northeast side of William Mooney Road



Photograph 2 ↑

Site 1 – Dry area where pool of standing water used to be on the northeast side of William Mooney Road



Photograph 3 ↑

Site 2 – Looking upstream, stream flows through farm fields before flowing through culvert



Photograph 4 ↑

Site 2 – Looking downstream, abundant riparian vegetation cover



Photograph 5 ↑

Site 3 – South Huntley Creek, west side of Carp Road, looking upstream (note: clear water)



Photograph 6 ↑

Site 3 – South Huntley Creek, east side of Carp Road, looking downstream before stream enters quarry property (note: clear water)



Photograph 7 ↑

Site 4 – South Huntley Creek, southeast side of Richardson Side Road, looking upstream (note turbid water)



Photograph 8 ↑

Site 4 – South Huntley Creek, northwest side of Richardson Side Road, looking downstream (note: turbid water, high water levels)



Photograph 9 ↑

Site 6 – South Huntley Creek, west side of Newill Place, looking upstream (note: low water levels)



Photograph 10 ↑

Site 6 – South Huntley Creek, east side of Newill Place, looking downstream (note: low water levels)



Photograph 11 ↑

Site 5 – Huntley Creek, west side of Oak Creek Road, looking upstream



Photograph 12 ↑

Site 5 – Huntley Creek, east side of Oak Creek Road, looking downstream